












f WYMIAR DO OSI SZYBY

B X2

b

$b = 1,25 \text{ cm}$
 $X2 = B - b$

g WYMIAR DO OSI SZYBY

X1

A

a

$a = 1,25 \text{ cm}$
 $X2 = A - a$

TABELA ROZMIARÓW:

CHROME

SYMBOL	WYMIAR	SZKŁO	A	B	C	H	X1*
K-0753	50x195	czyste 6mm	49,5-51	MAX 120	34	195	48,2-49,7
K-0754	50x195	czyste 6mm	49,5-51	MAX 120	54	195	48,2-49,7
K-0755	60x195	czyste 6mm	59,5-61	MAX 120	34	195	58,2-59,7
K-0756	60x195	czyste 6mm	59,5-61	MAX 120	54	195	58,2-59,7
K-0339	70x195	czyste 6mm	69,5-71	MAX 120	34	195	68,2-69,7
K-0340	70x195	czyste 6mm	69,5-71	MAX 120	54	195	68,2-69,7
K-0341	80x195	czyste 6mm	79,5-81	MAX 120	34	195	78,2-79,7
K-0342	80x195	czyste 6mm	79,5-81	MAX 120	54	195	78,2-79,7
K-0343	90x195	czyste 6mm	89,5-91	MAX 120	34	195	88,2-89,7
K-0344	90x195	czyste 6mm	89,5-91	MAX 120	54	195	88,2-89,7
K-0345	100x195	czyste 6mm	99,5-101	MAX 120	34	195	98,2-99,7
K-0346	100x195	czyste 6mm	99,5-101	MAX 120	54	195	98,2-99,7
K-0757	110x195	czyste 6mm	109,5-111	MAX 120	34	195	108,2-109,7
K-0758	110x195	czyste 6mm	109,5-111	MAX 120	54	195	108,2-109,7
K-0759	120x195	czyste 6mm	119,5-121	MAX 120	34	195	118,2-119,7
K-0760	120x195	czyste 6mm	119,5-121	MAX 120	54	195	118,2-119,7

* X1 - WYMIAR DO OSI SZYBY

BLACK

SYMBOL	WYMIAR	SZKŁO	A	B	C	H	X1*
K-0773	50x195	czyste 6mm	49,5-51	MAX 120	34	195	48,2-49,7
K-0774	50x195	czyste 6mm	49,5-51	MAX 120	54	195	48,2-49,7
K-0775	60x195	czyste 6mm	59,5-61	MAX 120	34	195	58,2-59,7
K-0776	60x195	czyste 6mm	59,5-61	MAX 120	54	195	58,2-59,7
K-0777	70x195	czyste 6mm	69,5-71	MAX 120	34	195	68,2-69,7
K-0778	70x195	czyste 6mm	69,5-71	MAX 120	54	195	68,2-69,7
K-0779	80x195	czyste 6mm	79,5-81	MAX 120	34	195	78,2-79,7
K-0780	80x195	czyste 6mm	79,5-81	MAX 120	54	195	78,2-79,7
K-0781	90x195	czyste 6mm	89,5-91	MAX 120	34	195	88,2-89,7
K-0782	90x195	czyste 6mm	89,5-91	MAX 120	54	195	88,2-89,7
K-0783	100x195	czyste 6mm	99,5-101	MAX 120	34	195	98,2-99,7
K-0784	100x195	czyste 6mm	99,5-101	MAX 120	54	195	98,2-99,7
K-0785	110x195	czyste 6mm	109,5-111	MAX 120	34	195	108,2-109,7
K-0786	110x195	czyste 6mm	109,5-111	MAX 120	54	195	108,2-109,7
K-0787	120x195	czyste 6mm	119,5-121	MAX 120	34	195	118,2-119,7
K-0788	120x195	czyste 6mm	119,5-121	MAX 120	54	195	118,2-119,7

* X1 - WYMIAR DO OSI SZYBY