












f

WYMIAR DO OSI SZYBY

B X2

b

b = 1 cm
X2 = B - b

g

WYMIAR DO OSI SZYBY

X1

A

a

a = 1,25cm
X2 = A - a

TABELA ROZMIARÓW:

LIGHT GOLD

SYMBOL	WYMIAR	SZKŁO	A	B	C	H	X1*
K-1959	50x195	czyste 6mm	49,5-51	MAX 120	34	195	48,2-49,7
K-1960	50x195	czyste 6mm	49,5-51	MAX 120	54	195	48,2-49,7
K-1961	60x195	czyste 6mm	59,5-61	MAX 120	34	195	58,2-59,7
K-1962	60x195	czyste 6mm	59,5-61	MAX 120	54	195	58,2-59,7
K-1963	70x195	czyste 6mm	69,5-71	MAX 120	34	195	68,2-69,7
K-1964	70x195	czyste 6mm	69,5-71	MAX 120	54	195	68,2-69,7
K-1965	80x195	czyste 6mm	79,5-81	MAX 120	34	195	78,2-79,7
K-1966	80x195	czyste 6mm	79,5-81	MAX 120	54	195	78,2-79,7
K-1967	90x195	czyste 6mm	89,5-91	MAX 120	34	195	88,2-89,7
K-1968	90x195	czyste 6mm	89,5-91	MAX 120	54	195	88,2-89,7
K-1969	100x195	czyste 6mm	99,5-101	MAX 120	34	195	98,2-99,7
K-1970	100x195	czyste 6mm	99,5-101	MAX 120	54	195	98,2-99,7
K-1971	110x195	czyste 6mm	109,5-111	MAX 120	34	195	108,2-109,7
K-1972	110x195	czyste 6mm	109,5-111	MAX 120	54	195	108,2-109,7
K-1973	120x195	czyste 6mm	119,5-121	MAX 120	34	195	118,2-119,7
K-1974	120x195	czyste 6mm	119,5-121	MAX 120	54	195	118,2-119,7

* X1 - WYMIAR DO OSI SZYBY

GOLD BRUSHED

SYMBOL	WYMIAR	SZKŁO	A	B	C	H	X1*
K-4329	50x195	czyste 6mm	49,5-51	MAX 120	34	195	48,2-49,7
K-4330	50x195	czyste 6mm	49,5-51	MAX 120	54	195	48,2-49,7
K-4331	60x195	czyste 6mm	59,5-61	MAX 120	34	195	58,2-59,7
K-4332	60x195	czyste 6mm	59,5-61	MAX 120	54	195	58,2-59,7
K-4333	70x195	czyste 6mm	69,5-71	MAX 120	34	195	68,2-69,7
K-4334	70x195	czyste 6mm	69,5-71	MAX 120	54	195	68,2-69,7
K-4335	80x195	czyste 6mm	79,5-81	MAX 120	34	195	78,2-79,7
K-4336	80x195	czyste 6mm	79,5-81	MAX 120	54	195	78,2-79,7
K-4337	90x195	czyste 6mm	89,5-91	MAX 120	34	195	88,2-89,7
K-4338	90x195	czyste 6mm	89,5-91	MAX 120	54	195	88,2-89,7
K-4339	100x195	czyste 6mm	99,5-101	MAX 120	34	195	98,2-99,7
K-4340	100x195	czyste 6mm	99,5-101	MAX 120	54	195	98,2-99,7
K-4341	110x195	czyste 6mm	109,5-111	MAX 120	34	195	108,2-109,7
K-4342	110x195	czyste 6mm	109,5-111	MAX 120	54	195	108,2-109,7
K-4343	120x195	czyste 6mm	119,5-121	MAX 120	34	195	118,2-119,7
K-4344	120x195	czyste 6mm	119,5-121	MAX 120	54	195	118,2-119,7

* X1 - WYMIAR DO OSI SZYBY

TABELA ROZMIARÓW:

COPPER BRUSHED

SYMBOL	WYMIAR	SZKŁO	A	B	C	H	X1*
K-2109	50x195	czyste 6mm	49,5-51	MAX 120	34	195	48,2-49,7
K-2110	50x195	czyste 6mm	49,5-51	MAX 120	54	195	48,2-49,7
K-2111	60x195	czyste 6mm	59,5-61	MAX 120	34	195	58,2-59,7
K-2112	60x195	czyste 6mm	59,5-61	MAX 120	54	195	58,2-59,7
K-2113	70x195	czyste 6mm	69,5-71	MAX 120	34	195	68,2-69,7
K-2114	70x195	czyste 6mm	69,5-71	MAX 120	54	195	68,2-69,7
K-2115	80x195	czyste 6mm	79,5-81	MAX 120	34	195	78,2-79,7
K-2116	80x195	czyste 6mm	79,5-81	MAX 120	54	195	78,2-79,7
K-2117	90x195	czyste 6mm	89,5-91	MAX 120	34	195	88,2-89,7
K-2118	90x195	czyste 6mm	89,5-91	MAX 120	54	195	88,2-89,7
K-2119	100x195	czyste 6mm	99,5-101	MAX 120	34	195	98,2-99,7
K-2120	100x195	czyste 6mm	99,5-101	MAX 120	54	195	98,2-99,7
K-2121	110x195	czyste 6mm	109,5-111	MAX 120	34	195	108,2-109,7
K-2122	110x195	czyste 6mm	109,5-111	MAX 120	54	195	108,2-109,7
K-2123	120x195	czyste 6mm	119,5-121	MAX 120	34	195	118,2-119,7
K-2124	120x195	czyste 6mm	119,5-121	MAX 120	54	195	118,2-119,7

* X1 - WYMIAR DO OSI SZYBY

GUNMETAL BRUSHED

SYMBOL	WYMIAR	SZKŁO	A	B	C	H	X1*
K-2265	50x195	czyste 6mm	49,5-51	MAX 120	34	195	48,2-49,7
K-2266	50x195	czyste 6mm	49,5-51	MAX 120	54	195	48,2-49,7
K-2267	60x195	czyste 6mm	59,5-61	MAX 120	34	195	58,2-59,7
K-2268	60x195	czyste 6mm	59,5-61	MAX 120	54	195	58,2-59,7
K-2269	70x195	czyste 6mm	69,5-71	MAX 120	34	195	68,2-69,7
K-2270	70x195	czyste 6mm	69,5-71	MAX 120	54	195	68,2-69,7
K-2271	80x195	czyste 6mm	79,5-81	MAX 120	34	195	78,2-79,7
K-2272	80x195	czyste 6mm	79,5-81	MAX 120	54	195	78,2-79,7
K-2273	90x195	czyste 6mm	89,5-91	MAX 120	34	195	88,2-89,7
K-2274	90x195	czyste 6mm	89,5-91	MAX 120	54	195	88,2-89,7
K-2275	100x195	czyste 6mm	99,5-101	MAX 120	34	195	98,2-99,7
K-2276	100x195	czyste 6mm	99,5-101	MAX 120	54	195	98,2-99,7
K-2277	110x195	czyste 6mm	109,5-111	MAX 120	34	195	108,2-109,7
K-2278	110x195	czyste 6mm	109,5-111	MAX 120	54	195	108,2-109,7
K-2279	120x195	czyste 6mm	119,5-121	MAX 120	34	195	118,2-119,7
K-2280	120x195	czyste 6mm	119,5-121	MAX 120	54	195	118,2-119,7

* X1 - WYMIAR DO OSI SZYBY