

SMART



NEW TRENDY Sp. z o.o.

Tel. 67 262 12 66


serwis@newtrendy.pl




www.newtrendy.pl

I-0668

v. 06

















ALTERNATYWNE WARIANTY SZYB

ALTERNATIVE VARIANTS OF THE GLASS










TABELA NIE DOTYCZY KABIN NA WYMIAR!

THE TABLE DOES NOT INCLUDE CUSTOM-MADE ENCLOSURES!


Gabaryty kabin **na wymiar** znajdują się na rysunku w zamówieniu.

Dimensions of the **custom-made** cabin are in the product order.


WYMIAR	A	H
130x200	128,5-131,5	200
140x200	138,5-141,5	200
150x200	148,5-151,5	200
160x200	158,5-161,5	200
170x200	168,5-171,5	200
180x200	178,5-182,5	200




2.1




2.2




2.3




2.4




2.5




3




3.1




4




4.1




4.2




5




5.1




5.2




6




6.1




6.2




7




7.1




7.2




8




8.1




8.2




8.3



9



9.1





9.2

Diagram 14 illustrates the application of silicone to the bottom of the case. A syringe labeled "TRANSPARENT SILICONE" is shown dispensing the material into the bottom of the case. A curved arrow indicates the direction of the application.


9.3

Diagram 9.3 illustrates the mounting of the bottom rail. The main view shows a corner of a window frame with a bottom rail being inserted into a channel. Two circular callouts provide detailed views. The top callout shows a cross-section of the rail (labeled 5R) being pushed into the channel (labeled 6) by a black arrow. A small black pin (labeled 14) is shown being inserted into the rail. The bottom callout shows the rail fully seated in the channel, with the pin (14) secured in place.


[illegible]




11.2




11.3




12




12.1




12.2




12.3




13




13.1









13.2




13.3

















18




19









24




25







26




26.1





27



28




29







✓ → 30


✗ → 22 / 12.1 / 13.1

30







32.2




33




34




34.1




34.2




35




35.1




35.2




35.3




35.4




36




36.1




36.2




36.3




37




37.1




37.2




37.3





38





39













NEW TRENDY Sp. z o.o.

Tel. 67 262 12 66

serwis@newtrendy.pl

www.newtrendy.pl